

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans **Run date** 19-Nov-14 **Time** 5:50 PM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 096 Const Calendar Day: 311 Date: 16-Jul-2010 Friday
Inspector Name: Bruce, Matt Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 06:30 am 03:00 pm Break: 00:30 Over Time:

Federal ID: Location:

Reviewer: Mathur, Lalit Approved Date: 08-Oct-10 Status: Approved

Weather

04-0120F4

Temperature 7 AM 60 - 70 **12 PM** 60 - 70 **4PM** 60 - 70

X-W2C-BCT.034

Precipitation 0.00" Condition Mostly sunny to partly overcast.

Working Day V If no, explain:

Bid Item: 034

3 3 5	
Diary:	Dispute
Work description.	
- Continued to work on pertinent paperwork related to the stressing the W-Line continuity tendons and	
strand placement.	

E-W Line Cross Over W2 Cap Cap Beam Continuity Tendons

SCHWAGER DAVIS INC. Labor									
Contractor:	SCHWAGER DAVIS	INC.							
Ironworker	JNM	Bobby Almon	0.00	0.00	0.00	0.00			
Ironworker	JNM	Marty Murillo	0.00	0.00	0.00	0.00			
Ironworker	JNM	Bounthaby Singharath	0.00	0.00	0.00	0.00			
Ironworker	FOR	Erin Jones	0.00	0.00	0.00	0.00			
Ironworker	JNM	Brian Nobile	0.00	0.00	0.00	0.00			
Ironworker	GEN	Ralph Craig	0.00	0.00	0.00	0.00			
Ironworker	JNM	James Bond	0.00	0.00	0.00	0.00			

Diary: Dispute

Work description. 034 X-W2C-BCT.034

- Stressed continuity tendons W1B to W14B, W30 to W33B, W35B to W37B, W39B to W41B, and W44 with the multistrand ram CH600-8-109 using gauge CH600-8-109 A.Caltrans strain indicator number 59432 was used to track the load imposed upon the strands from the ram mentioned above. The ram calibration monitoring was done for continuity tendon W31B and the load was close to the curves submitted by Schwager Davis Inc. The elongations of the tendons stressed today were acceptable and no slip was observed. However at times the ironworkers were complacent measuring the elongations and just reciting theoretical values after tendon stressing was completed.
- Stressed continuity tendon W34B with the monostrand ram 6-8-134 using gauge 6-8-134A.
- Stressed continuity tendon W38B with the monostrand ram 6-8-0014 using gauge 6-8-0014A.
- Continued placing anchorheads and wedges for the live + dead ends of the WB continuity tendons.
- Began cutting the live + dead end tails of the WB continuity tendons already stressed.

The following is the list of equipment that SDI has onsite since it is not currently inputted into PMIV:

Stressing Rams: 6-8-0014, 6-8-134, 6-8-141, and CH600-8-109

Hydraulic Pumps for Monostrand Rams: 3 units with no designated numbers on the equipment Hydraulic Pumps for Multistrand Rams: 1 unit with no designated numbers on the equipment



Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name: Bruce, Matt Diary #: 096 Date: 16-Jul-2010 Friday

Hydraulic Pump for Pushing Strand: HPU-D-110-3K-02 Strand Pusher: No number designated on the equipment

Plasma Cutter (Hyperthern Powermax 1000G3 Series): No number designated on the equipment

- Refer to other Caltrans inspectors diaries for ABF and subcontractors operations and equipment at the W2 cap beam.

Attachment



Progress of the W2 precast slab done by Conco carpenters, see Lalits diary for more details.



SDI ironworkers positioning the multistrand ram to stress CT-W14B.



Stressing continuity tendon W14B.



Strand elongation measured at Pjack of 4 1/4" prior to the anchor set of a WB continuity tendon.

